

TABLE VIII
 NUMBER OF HALEY & ALDRICH SOIL SAMPLES TESTED BY SOIL TYPES
 MILL ROCK PARK, SEWER PUMP STATION AND ROCHFORD FIELD
 HAMDEN, CONNECTICUT

Depth of Sample (ft)	Earthen Fill	Miscellaneous Fill	Domestic Refuse Fill	Industrial Waste Fill	Alluvial Sediments	Glaciodeltaic Deposits	Glacial Till
Mill Rock Park							
0-2	32	3	--	8	--	--	--
2-4	6	7	3	18	--	--	--
4 – Water Table	--	9	2	13	1	2	--
Below Water Table	--	4	1	11	18	9	--
Sewer Pump Station							
0-2	4	--	--	--	--	--	--
2-4	3	--	--	--	--	--	--
4 – Water Table	--	--	1	--	--	--	--
Below Water Table	--	--	--	--	--	1	--
Rochford Field							
0-2	24	5	2	--	--	--	--
2-4	6	15	8	--	--	--	--
4 – Water Table	--	10	14	--	6	2	3
Below Water Table	--	1	1	--	11	8	1